
Technical Service Bulletin

Model 70LP Actuator's required the use of a e-clip/retaining ring, to retain the actuator pin to the bushings, and actuator rollers. We are no longer using the 48795 actuator pin.



TIE DOWN ENGINEERING • 5901 Wheaton Drive • Atlanta GA, 30336 www.tiedown.com • (404) 344-0000 • FAX (404) 349-0401



20505,C835